PAGE: 1

PRINT DATE: 11/21/91

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL HARDWARE

\$0502

NUMBER: 04-2-MD14-IM-X

M-X ATTACHMENT

PAGE 46 OF

SUBSYSTEM MANE: AUXILIARY POWER UNIT (APU)

ä

REVISION: 3 11/21/91

PART NAME VENDOR NAME

PART KUMBER

■ SRU

COUPLING

VENDOR MUMBER

SYMETRICS

MC621-0038-0500/0300

592002

PART DATA

- EXTENDED DESCRIPTION OF PART UNDER AMALYSIS:

  COUPLING, APU GEARBOX LUBE OIL FILL (MOX6), VENT (MOX5), DRAIN (MDX4),

  LUBE OIL SEAL CAVITY DRAIN (TPX9), PURGE (TPX8) AND WATER SPRAY

  BOILER LINE (MDX7)
- QUANTITY OF LIKE ITEMS: 18 ONE AS DESCRIBED ABOVE PER APU
- # FUNCTION:
  - (1) TO PROVIDE INTERFACE BETWEEN GROUND SERVICING EQUIPMENT AND APU FOR LUBE OIL SERVICING.
  - (2) TO MAINTAIN PROPER SEAL AFTER SERVICING AND CHECKOUT.

PAGE: PRINT DATE: 11/21/91 FAILURE MODES EFFECTS AMALYSIS (FMEA) -- CRITICAL FAILURE MODE \$6502700 NUMBER: 04-2-MD14-IM-13 ATTACKHEN PAGE 47 5 REVISION# 3 11/21/91 R SUBSYSTEM: AUXILIARY POWER UNIT (APU) CRITICALITY OF THIS ITEM KAME: COUPLING FAILURE MODE: 1R3 # FAILURE MODE: EXTERNAL LEAKAGE **MISSION PHASE:** PL PRELAUNCH LO LIFT-OFF 00 ON-CRBIT DE-ORBIT 90 L\$ LANDING SAFING VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA 103 DISCOVERY 104 **SITKAJTA** ENDEAVOUR CAUSE: SEAL DAMAGE, PIECE-PART FAILURES, CORROSION, CONTAMINATION = CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO REDUNDANCY SCREEN A) FAIL B) FAIL C) PASS

PASS/FAIL RATIONALE:

FCAP SEAL IS NOT READILY CAPABLE OF CHECKOUT IN THE FIELDS

EXIST. COTTON AS NO MEASUREMENT BETWEEN POPPET AND CAP SEALS AND EXIST.

**■** ¢)

Ġ.

PAGE:

(A) DESIGN:

PRINT DATE: 11/21/91

FAILURE MODES EFFECTS ANALYSIS (FMEA) CRITICAL FAILURE MODE NUMBER: 04-2-MD14-IM-13	
	PAGE 48 OF
C171 HER EPPEARS	

## - FAILURE EFFECTS \_

- (A) SUBSYSTEM: POSSIBLE LOSS OF ONE APU SYSTEM BEFORE MISSION COMPLETION.
- OR DUMPING OF (B) INTERFACING SUBSYSTEM(5): POSSIBLE LOSS OF SHAFT POWER TO ONE HYDRAULIC PUMP, LUBE OIL IN AFT COMPARTMENT.
- (C) MISSION: ABORT DECISION IS REQUIRED, IF FAILURE OCCURS PRIOR TO ENTRY COMMITMENT.
- (D) CREW, VEHICLE, AND ELEMENT(S): NO EFFECT UNLESS SECOND APU SYSTEM IS LOST. LUBE OIL IGNITION IS CONSIDERED UNLIKELY SINCE ALL APU SYSTEM HOT SURFACES ARE INSULATED AND GAPS ARE COVERED WITH ALUMINIZED TAPE. (IGNITION TEMPERATURE IS 760 DEG F). POSSIBLE FIRE/EXPLOSION DUE TO HYDRAZINE IN AFT COMPARTMENT IF FUEL PUMP SHAFT SEAL LEAKS AND DUAL SEALS SEPARATING FUEL AND OIL CAVITY LEAK.
- (E) FUNCTIONAL CRITICALITY EFFECTS: IST FAILURE - LEAKAGE OF OIL PAST DUAL POPPET SEALS NO EFFECT. 2ND FAILURE - LEAKAGE OF OIL PAST CAP SEAL RESULTING IN LOSS OF CUBRICATION AND APU. 3RD FAILURE - LOSS OF SECOND APU RESULTING IN LOSS OF CREW/VEHICLE. - DISPOSITION RATIONALE -
  - COUPLING IS CONSTRUCTED OF 17-4PH CRES WITH A SPRING MADE OF 17-7 PH.

THE POPPET AND CAP SEALS BACK UP EACH OTHER AND ARE FLUOROCARBON O'RINGS. THE END FITTING IS A DUAL SEAL DYNATURE OF 17-4 PH CRES. HEAT TREATED 145 KSI TENSILE.

■ (B) TEST: THE COUPLING AND CAP ARE LEAK CHECKED AND PROOFED DURING ATP. THE COUPLING AND CAP WITHSTOOD 500 PSIG BURST TEST AT 160 DEG F AND VIBRATED AT 22G RMS. A CAPPED COUPLING WAS TESTED UNDER THERMAL  $De_{\mathcal{L}}$ VACUUM CONDITION (360 DEG F) WITH LUBE OIL. DYNATUBE FITTING QUALIFIED BY RESISTOFLEX FOR 200,000 IMPULSE CYCLES UP TO 4,500 PSI AT 400 DIS F -65 DEG F, 12,000 PSI BURST PLUS SINE VIBRATION AT +/- 0.416 TO +/-10 G FOR 3 HR IN 20 MIN SWEEPS FROM 6 - 2000 CPS. POMRSD: PRESSURE DECAY LEAK TEST ON LUBE SYSTEM IS PERFORMED AFTER SERVICING

 $\Delta A = 7 - 158$ 

PAGE:

PRINT DATE: 11/21/91

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE

NUMBER: 04-2-H014-[H-13

SOSOZFO ATTACHMET PAGE 49 T

EVERY FLOW.

(C) INSPECTION:
 RECEIVING INSPECTION
 MATERIAL AND PROCESSES CERTIFICATIONS ARE VERIFIED.

CONTAMINATION CONTROL
CLEANLINESS TO LEVEL 100 IS VERIFIED BY INSPECTION. PARTS PASSIVATION
AND OTHER CORROSION PROTECTION REQUIREMENTS ARE VERIFIED BY INSPECTION.

ASSEMBLY/INSTALLATION.
MANUFACTURING, ASSEMBLY, AND [HSTALLATION REQUIREMENTS ARE VERIFIED BY INSPECTION. CRITICAL DIMENSIONS AND SURFACE FINISHES ARE VERIFIED BY INSPECTION.

CRITICAL PROCESSES
HEAT TREATMENT IS VERIFIED BY INSPECTION, INCLUDING ROCKWELL HARDNESS
TEST.

TESTING
TEST EQUIPMENT AND TOOL CALIBRATION ARE VERIFIED BY INSPECTION. ATP IS WITNESSED AND VERIFIED BY INSPECTION.

HANOLING/PACKAGING HANOLING, PACKAGING, STORAGE, AND SHIPPING PROCEDURES ARE VERIFIED.

(D) FAILURE HISTORY: TEST POINT OD LEAKED DURING SEAL CAVITY DRAIN FLUSH (CAR AC5748). LEAKAGE WAS CAUSED BY A CONTAMINANT OF UNKNOWN SOURCE.

\* (E) OPERATIONAL USE: SHUT DOWN APU BASED ON SYSTEM TEMPERATURES AND FLIGHT PHASE. REMAINING

- APPROVALS -

RELIABILITY ENGINEERING: D. R. ATAPATTU
DESIGN ENGINEERING : J. R. MUHROE
QUALITY MANAGER : D. J. BUTTNER
HASA RELIABILITY : The per 1/24/92
HASA SUBSYSTEM MANAGER :

HASA QUALITY ASSURANCE :

.